



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com)
Submission Date:	Apr 14, 2020 11:27:45 AM MDT
Server Receive Date:	Apr 14, 2020 3:48:02 PM MDT
Reference Number:	20200414-18139443038
Location:	41 Cassidy Dr, Durango, CO 81303, USA
	Apr 14, 2020 11:23:43 AM MDT [ <a href="#">View Map</a> ]

## Information

Name	kenneth.canterbury@crossfire-llc.com
Date	Apr 9, 2020
API Number	50670557700 <span style="color: red;">API correction: 05-067-07002</span>
Action Complete	Seeding Erosion Repairs Install Rock Run Down Clean Up Land Owner Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

Seeded bare areas

Photo of second corrective action completed



Completed work description of corrective action 2

Picked up trash / old wattles

Photo of third corrective action completed



Completed work description of corrective action 3  
Photo of fourth corrective action completed



Completed work description  
Completed work description of corrective action 4  
Summary of all work completed

Installed rock run down

Seeded bare area  
Picked up trash  
Installed rock run down, picked up trash , seeded bare areas.