



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Apr 17, 2020 5:32:43 PM MDT
Server Receive Date:	Apr 17, 2020 5:35:56 PM MDT
Reference Number:	20200417-18139889757
Location:	557 Airpark Dr, Durango, CO 81303, USA Apr 17, 2020 5:32:25 PM MDT [View Map]

Information

Name	colen@horizonenvservices.com
Date	Apr 15, 2020
Well Name	MARTIN, PAUL GAS UNIT A 2
Location Name (Other)	A3 and A4
API Number	50670866200
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Other

Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

treated Russian knapweed

Photo of third corrective action completed



Completed work description of corrective action 3

Completed work description of corrective action 4

treated musk thistle

treated noxious weeds in reclamation area and pipeline right of way

Additional photos



Additional photos



Summary of all work completed

previous treatment dates 6/17/16, 7/7/17, 7/2/18, 7/3/19