



Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Apr 21, 2020 1:48:36 PM MDT
Server Receive Date:	Apr 21, 2020 1:51:44 PM MDT
Reference Number:	20200421-18140309608
Location:	557 Airpark Dr, Durango, CO 81303, USA Apr 21, 2020 1:48:06 PM MDT [ <a href="#">View Map</a> ]

Information

Name	colen@horizonenvservices.com
Date	Apr 20, 2020
Well Name	LUCERO GAS UNIT 2
API Number	50670882600
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Other

Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

treated musk thistle rosettes

Photo of third corrective action completed



Completed work description of corrective action 3  
Photo of fourth corrective action completed

treated musk thistle rosettes



Completed work description  
Completed work description of corrective action 4  
Additional photos

treated musk thistle  
treated noxious weeds



Completed work description  
Summary of all work completed

treated noxious weeds  
previous treatment dates 7/8/16, 7/21/17, 6/11/18,  
4/22/19