

Inspection Photos
Location Name: LePLATT 33-34
API#: 05-071-07329
INSP. #: 695102739



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN

Inspection Photos
 Location Name: LePLATT 33-34
 API#: 05-071-07329
 INSP. #: 695102739

Calibration Report

Report Date: 4/26/20 AM Collection Time: 11:34 AM

Source ID: Location: System: Contact # 718-646-7688
 Field: Raton Basin
 State: Colorado
 Producer: Evergreen Natural Resources
 Purchaser: Colorado Interstate Gas

Gas Meter Details:
 Street Tube Size: 2.000
 Pipe Size: 2.000
 Approx. P. Pressure: 12.00
 Pressure Base: 12.00
 Inlet Type: 1/2" NPT
 Inlet Location: 1/2" NPT
 Temperature Bias: 0.00
 Temperature Bias: 0.00
 Specific Gravity: 0.550

Inspection Results:
 Plate Inspected? Yes No Dirty? Yes No Nipped? Yes No
 Gasket Sharp? Yes No Plate Weld? Yes No Warped? Yes No
 Gasket Ring Damaged? Yes No Filled? Yes No Bevel Downstream? Yes No
 Tube Inspected? Yes No Nipped? Yes No
 Dirty? Yes No
 Flared? Yes No

DIFFERENTIAL				STATIC PRESSURE				TEMPERATURE			
FOUN.	LEFT	FOUN.	LEFT	FOUN.	LEFT	FOUN.	LEFT				
10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00				
15.00	15.00	15.00	15.00	15.00	15.00	15.00	15.00				
20.00	20.00	20.00	20.00	20.00	20.00	20.00	20.00				
25.00	25.00	25.00	25.00	25.00	25.00	25.00	25.00				
30.00	30.00	30.00	30.00	30.00	30.00	30.00	30.00				
35.00	35.00	35.00	35.00	35.00	35.00	35.00	35.00				
40.00	40.00	40.00	40.00	40.00	40.00	40.00	40.00				

Cal. Range: 0 to 100
 Gas Sample Taken: 0.00
 HSB analysis done: 0.00
 PPM or %: 0.00
 HSB Analysis Done: 0.00

REMARKS: 37.12644, -104.76418, 2039.0m, 102°
 2020/04/27 15:07:35

PHOTO 3: GAS METER CAL. REPORT.