

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402382100

Date Received:

04/27/2020

Spill report taken by:

CHESSON, BOB

Spill/Release Point ID:

475523

## SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

### OPERATOR INFORMATION

Name of Operator: <u>BONANZA CREEK ENERGY OPERATING COMPANY LLC</u>	Operator No: <u>8960</u>	<b>Phone Numbers</b>
Address: <u>410 17TH STREET SUITE #1400</u>		Phone: <u>(720) 315-8934</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>
Contact Person: <u>Luke Kelly</u>		Mobile: <u>( )</u>
		Email: <u>LKelly@bonanzacrk.com</u>

### INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 402374816

Initial Report Date: 04/19/2020 Date of Discovery: 04/18/2020 Spill Type: Recent Spill

#### Spill/Release Point Location:

QTRQTR SWSW SEC 36 TWP 4N RNG 63W MERIDIAN 6

Latitude: 40.262507 Longitude: -104.392619

Municipality (if within municipal boundaries): \_\_\_\_\_ County: WELD

#### Reference Location:

Facility Type: FLOWLINE SYSTEM ☒ Facility/Location ID No 422497

Spill/Release Point Name: FL 4-63-36 1B Pipe Rack ☐ Well API No. (Only if the reference facility is well) 05- -

☐ No Existing Facility or Location ID No.

#### Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

*Secondary containment, **including walls & floor regardless of construction material**, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

Were Five (5) barrels or more spilled? No

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): >=1 and <5

Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): 0

Estimated Other E&P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: \_\_\_\_\_

#### Land Use:

Current Land Use: NON-CROP LAND Other(Specify): \_\_\_\_\_

Weather Condition: Overcast, 30's

Surface Owner: STATE Other(Specify): \_\_\_\_\_

#### Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

*As defined in COGCC 100-Series Rules*

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

A fitting on an aboveground flowline pipe rack allowed approximately 1.5 bbls of oil to be released to the ground outside of containment. Roustabouts were dispatched to remove the impacted soil. Confirmation soil samples will be collected and submitted for laboratory analysis. Analytical results will be included in a supplemental eForm 19.

**List Agencies and Other Parties Notified:**

**OTHER NOTIFICATIONS**

Date	Agency/Party	Contact	Phone	Response
4/19/2020	Weld County OEM	Roy Rudisil	-on file	Notified of release via OEM report
4/19/2020	Surface Owner	SLB - Steve Freese	-on file	Notified of release

Was there a Grade 1 Gas Leak? Yes ☐ No ☒

If YES, enter the Document Number of the Grade 1 Gas Leak Report Form 44: \_\_\_\_\_

Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? Yes ☐ No ☒

If YES, enter the Document Number of the Initial Accident Report, Form 22: \_\_\_\_\_

Was there damage during excavation? Yes ☐ No ☒

If YES, was CO 811 notified prior to excavation? Yes ☐ No ☐

**SPILL/RELEASE DETAIL REPORTS**

#1	Supplemental Report Date: 04/27/2020		
<b>FLUIDS</b>	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	1	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	0	0	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO			
Secondary containment, <b>including walls &amp; floor regardless of construction material</b> , must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.			
<b>A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit</b>			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): 10		Width of Impact (feet): 15	
Depth of Impact (feet BGS): _____		Depth of Impact (inches BGS): _____	
How was extent determined?			
The extent was determined through visual delineation.			
Soil/Geology Description:			
Valent sand, 3-9% slopes			
Depth to Groundwater (feet BGS) 35		Number Water Wells within 1/2 mile radius: 0	

If less than 1 mile, distance in feet to nearest Water Well 2855 None ☐ Surface Water None ☒  
Wetlands None ☒ Springs None ☒  
Livestock None ☒ Occupied Building None ☒

Additional Spill Details Not Provided Above:

The fitting was replaced and the impacted soil was immediately removed and hauled to a COGCC approved disposal facility. Confirmation soil samples will be collected and submitted for laboratory analysis. Analytical results will be included in a subsequent eForm 19.

## REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

Basis for Closure: ☐ Corrective Actions Completed (documentation attached)

☐ Work proceeding under an approved Form 27

Form 27 Remediation Project No: \_\_\_\_\_

## OPERATOR COMMENTS:

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Luke Kelly

Title: Senior Env. Specialist Date: 04/27/2020 Email: LKelly@bonanzacrk.com

## COA Type

## Description

--	--

## Attachment Check List

### Att Doc Num

### Name

402382100	SPILL/RELEASE REPORT(SUPPLEMENTAL)
402382263	SITE MAP
402382321	FORM 19 SUBMITTED

Total Attach: 3 Files

## General Comments

### User Group

### Comment

### Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)