

Inspection Photos

Location Name: BRIGGS-66N64W /33SWSE

Location #: 332080



Photo #1

Briggs 15-33 (05-123-21809) Wellsite

Plugged & Abandoned | PA

~ 35 yds.

Reclamation progressing



Photo #2

Briggs 15-33, Webster 10-33 Battery site

Abandoned: Unused Equipment

Gas meter run & riser



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources