

Inspection Photos
Location Name: Kenneth E Koch #1
Location ID: 333164



Photo 1 WH

Photo 2 Debris: dead weeds around well head and on location.

Inspection Photos
Location Name: Kenneth E Koch #1
Location ID: 333164



Photo 3 Debris: dead weeds on location. Unused equipment: cement PU base not in use



Photo 4 Debris: Dead weeds around well head and on location.