

Inspection Photos

Loc#417608

Operator: Grizzly

Inspection Number: 692402118

Inspection Date: 4/22/2020





Photo#1:
Overview of location to South.

April 22, 2020




Photo#2:
Staining at Wellhead.

April 22, 2020



Photo#3:
Surface Owner stored equipment.

Grizzly GGU Daley Loc#417608



Photo#4:

Open cellars/cans; insert of dead small mammal drowned in cellar storm water.

Photo#5:

April 22, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly GGU Daley Loc#417608