

Inspection Photos
Location Name: State 1-36 1
Location ID: 324625



Photo 1. Tanks remain on location.



Photo 2. Pump jack and separation equipment remain on location.



Inspection Photos
Location Name: State 1-36 1
Location ID: 324625



Photo 3. Separation equipment and excavation work remain on location and incomplete.



Photo 4. Pump jack and excavation work remain on location and incomplete.

