

Inspection Photos
Location Name: Dill Gulch 1-22
Location ID: 434520



Photo 1. Overview of location taken facing west.



Photo 2. Gauge hatch open on tank.

