

Inspection Photos  
Long Ridge J15  
Spill/Release ID: 474500  
Inspection Date: April 23, 2020



LR J15 Location sign



Stockpiled material on the J15 location looking northeast



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Long Ridge J15**  
**Spill/Release ID: 474500**  
**Inspection Date: April 23, 2020**



**Stockpiled material on the J15 location looking southwest**



**View of the excavation, 4-inch and 8-inch pipeline**





**Inspection Photos**  
**Long Ridge J15**  
**Spill/Release ID: 474500**  
**Inspection Date: April 23, 2020**



**View of the excavation**



**View of the pig chute and valve can (red circle) where the 4-inch pipeline was installed**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources