

Pit Status Evaluation Form

Pit Overview:

Pit Name: FRANCIS D. CLARK "B" UNIT	Facility ID: 118575
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: AMOCO PRODUCTION COMPANY / 2500	
Updated Operator:	
Form 15 Pit Permit Doc #: 582422	Permit Date: 8/25/1973
Related Facilities: FRANCIS D. CLARK UNIT B #1 (API 123-07740; Facility ID 239952; Loc ID 317773)	

County: WELD			
Township: 1N	Range: 67W	Section: 14	QQ: NESW
Original Latitude/ Longitude: 40.049158 / -104.865052			
Updated Latitude/ Longitude: /			
Basis for Location Change:			
Corrected QQ based on pit permit			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|------------------|
| <input checked="" type="checkbox"/> | Form 15 Pit Permit – Doc #: 582422 | Date: 8/25/1973 |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 40051 | Date: 12/18/1997 |
| | Doc #: 40050 | Date: 1/18/1999 |
| | Doc #: | Date: |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input checked="" type="checkbox"/> | COGIS Document – Doc #: 582423 | Date: 4/9/1979 |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2142986 | Date: 8/21/1997 |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

1979 Certificate of Clearance notes water goes to tank

Pit Status Review Summary:

Based on records review, any pits on location were replaced by a tank prior to 4/30/1979 certificate of clearance, which states that produced water goes to a storage tank. 1997 pit inventory documents a 75bbl fiberglass tank on location. Pit status has been changed to closed.