

**Inspection Photos**  
**Location Name: Buxman 1-33**  
**Location ID: 322699**



**Photo 1: Wellhead sign**



**Photo 2: Wellhead**

Inspection Photos  
Location Name: Buxman 1-33  
Location ID: 322699




Photo 3: Tank battery Sign



Photo 4: Tank Battery; inadequate berm





**Inspection Photos**  
**Location Name: Buxman 1-33**  
**Location ID: 322699**



**Photo 5: H2O tank not anchored.**



**Photo 6: Separator not anchored**

