

Inspection Photos
Location Name: Lowell-Paul Dairy 1-33
Location ID: 322671




Photo 1: Tank Battery Sign



Photo 2: Tank Battery

Inspection Photos
Location Name: Lowell-Paul Dairy 1-33
Location ID: 322671



Photo 3: Separator anchored



Photo 4: Bucket removed