

Inspection Photos
Location Name: Klein(Lanyard Extention)24-8
Location ID: 318615



Photo 1 WH sign

Photo 2 WH trash removed and weeds have been cut down

Inspection Photos
Location Name: Klein(Lanyard Extention)24-8
Location ID: 318615



Photo 3 Weeds have been removed from around well site

Photo 4 TB sign

Inspection Photos
Location Name: Klein(Lanyard Extention)24-8
Location ID: 318615



Photo 5 TB

Photo 6 Horizontal Heated Separator

Inspection Photos
Location Name: Klein(Lanyard Extention)24-8
Location ID: 318615



Colorado Oil & Gas Conservation Commission
Co Rd 22, Roggen, CO 80662, USA
40.14752, -104.3556, 4683.611, 82
04/28/2020 10:02:29



Colorado Oil & Gas Conservation Commission
Co Rd 22, Roggen, CO 80662, USA
40.14749, -104.35544, 4680.111, 117
04/28/2020 10:02:45

Photo 9 area where flow line work was done. Sink hole developing.

Photo 10 sink hole where flow line work was done needs to be filled and packed