

Inspection Photos

Location Name: Puckett 697-26A Pad

Location ID: #416157

Inspection Date: April 24, 2020



Photo #1 – Sign at entrance to pad.



Photo #2 – View of fluids inside of tank battery secondary containment area (east side). Note hoses stored inside of secondary containment area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Puckett 697-26A Pad

Location ID: #416157

Inspection Date: April 24, 2020



Photo #3 – Mixed fluids, hoses with metal fittings, and wood debris inside of tank battery secondary containment area (SE corner). Note presence of condensate floating on fluids (red arrow). Hydrocarbon odors were observed in this area.



Photo #4 – Aerial photograph of tank battery documents the amount of fluids present in secondary containment area during inspection.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Puckett 697-26A Pad

Location ID: #416157

Inspection Date: April 24, 2020



Photo #5 – Aerial view of cut slope on east side of pad. Beneficial reuse of cuttings described in doc #402163214 has not been completed.



Photo #6 –Overview of land treatment area in southwest side of pad. Land treatment of cuttings is documented under Remediation Project #11653, which was approved for closure on 10/9/2018 (doc #401752256).



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Puckett 697-26A Pad
Location ID: #416157
Inspection Date: April 24, 2020



Photo #7 – Trash and debris located at valve can at south end of pad.



Photo #8 – Trash along west side of land treatment unit. (1)

Inspection Photos

Location Name: Puckett 697-26A Pad

Location ID: #416157

Inspection Date: April 24, 2020



Photo #9 - Trash along west side of land treatment unit. (2)



Photo #10 – Trash along north side of land treatment unit.



Inspection Photos

Location Name: Puckett 697-26A Pad

Location ID: #416157

Inspection Date: April 24, 2020



Photo #11 – Trash and stained soil located beneath culvert at north end of pad. Hydrocarbon odors were observed in the dark soil at this location (red arrow). Operator was notified of this issue via phone on 4/24/2020.

