

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/24/2020

Submitted Date:

04/28/2020

Document Number:

688307713

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
320716 _____ Sherman, Susan _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 74165
Name of Operator: RENEGADE OIL & GAS COMPANY LLC
Address: 6155 S MAIN STREET #225
City: AURORA State: CO Zip: 80016

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Ingve, Ed	303-829-2354	ed@renegadeoilandgas.com	All Inspections
Condill, JB	303-680-4725	jbrog@aol.com	All Inspections
Espinosa, Bill	(303) 829-4982	billespinosa30@yahoo.com	All Inspections
Burn, Diana		diana.burn@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204637	WELL	TA	04/26/1976	SI	005-06722	CHAMPLIN 126 AMOCO F 1	TA

General Comment:

[Annual Bradenhead Test Inspection](#)

Per COA, last approved Form 4 TA: 04 401824810 1/9/2019 This approval is good for one year and a new application must be made before September 30, 2019. Updates for the planned utilization of the well should be included with the application.

Obervation: [Subdivision and gas line stakes in field with "F" wells.](#)

Inspected Facilities

Facility ID: 204637 Type: WELL API Number: 005-06722 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Comment: Annual Bradenhead Test
 Bradenhead has slight blow that died immediately, Tubing 0 psi, Casing 0 psi, prior to test.
 Bradenhead stayed 0 psi during test and had ISIP of 0 psi at the end of test.
 Form 17 was signed by operator and inspector and operator has uploaded the Form 17 to COGCC database: 402378247 17 -00 APPROVED 04/28/2020 RENEGADE OIL & GAS COMPANY LLC

Corrective Action: Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688307743	Renegade Oil & Gas Champlin 126 Amoco F 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5135849