

Inspection Photos

Location Name: WIDO WOMAN 42-7 FOLLOW UP

API#: 05-071-07788

INSP. #: 695102749



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN

Inspection Photos
Location Name: WIDO WOMAN 42-7 FOLLOW UP
API#: 05-071-07788
INSP. #: 695102749

Calibration Report

Report Date: 7/17/19 11:04 AM Collection Date: 7/17/19 11:02 AM

Device ID: 102107788 System: Contact 8 719 848-7898

Location: Wido Woman Federal 42-7 Field: Raton Basin

State: Colorado

Inspector: Evergreen Natural Resources

Purchaser: Colorado Interstate Gas

Gas Properties

Current Flow Rate: 0.121 Tps Type: Factual Specific Gravity: 0.543

Pipe Size: 2.000 BP Tag Location: Down Stream

Alarm Pressure: 11.80 Temperature Base: 2.5

Pressure Base: 11.73 Temperature Base: 30

Inspection Details

Meter Inspected? Yes No Dirty? Yes No

Edges Sharp? Yes No

Seal Ring Damaged? Yes No

Table Inspected? Yes No

Dirty? Yes No

Pitted? Yes No

Static and Temperature Data

STATIC HEAD				TEMPERATURE			
Pressure	Temp	Static Head	Temp	Pressure	Temp	Static Head	Temp
0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00
2.00	2.00	2.00	2.00	2.00	2.00	2.00	2.00
3.00	3.00	3.00	3.00	3.00	3.00	3.00	3.00
4.00	4.00	4.00	4.00	4.00	4.00	4.00	4.00
5.00	5.00	5.00	5.00	5.00	5.00	5.00	5.00
6.00	6.00	6.00	6.00	6.00	6.00	6.00	6.00
7.00	7.00	7.00	7.00	7.00	7.00	7.00	7.00
8.00	8.00	8.00	8.00	8.00	8.00	8.00	8.00
9.00	9.00	9.00	9.00	9.00	9.00	9.00	9.00
10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00

Calibration Data

Cal Range: 0.00 to 1.00

Gas Sample Taken: Yes No

H2O Analysis Done: Yes No

H2O Analysis Done: Yes No

Coordinates

37.10187, -104.7056, 2095.0m, 317°

2020/04/28 14:24:17

PHOTO 3: GAS METER CAL. REPORT