

Inspection Photos
Location Name: Hiner 36 Pad
Location ID: 432252



Photo 1: Tank Battery Sign



Photo 2: Tank Battery



Inspection Photos
Location Name: Hiner 36 Pad
Location ID: 432252



Photo 3: Trash, unused risers



Photo 4: Equipment removed

