

FORM
5Rev
02/20**State of Colorado**
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401499179

Date Received:

09/06/2018

DRILLING COMPLETION REPORT

Per Rule 308A, this form and all required attachments shall be submitted after completing the drilling operations to drill, sidetrack, or deepen a wellbore and after changing the casing and/or cement configuration of a wellbore. If any attempt has been made to test, complete, or produce the well, the operator shall also submit a Form 5A (Completed Interval Report) per Rule 308B. If the well has been plugged, the operator shall also submit a Form 6 (Well Abandonment Report) per Rule 311.

Completion Type ☒ Final completion ☐ Preliminary completion

OGCC Operator Number: 10456

Contact Name: Reed Haddock

Name of Operator: CAERUS PICEANCE LLC

Phone: (720) 544-3267

Address: 1001 17TH STREET #1600

Fax: (303) 565-4606

City: DENVER

State: CO

Zip: 80202

Email: rhaddock@caerusoilandgas.com

API Number 05-045-23398-00

County: GARFIELD

Well Name: Puckett

Well Number: 12C-26-697

Location: QtrQtr: SENW Section: 26 Township: 6S Range: 97W Meridian: 6
FNL/FSL FEL/FWL

Footage at surface: Distance: 2257 feet Direction: FNL Distance: 1656 feet Direction: FWL

As Drilled Latitude: 39.495046 As Drilled Longitude: -108.190869

GPS Data: GPS Quality Value: 1.4 Type of GPS Quality Value: Date of Measurement: 10/02/2017

GPS Instrument Operator's Name: Bart Hunting, C.R.

FNL/FSL

FEL/FWL

** If directional footage at Top of Prod. Zone Dist: 1808 feet Direction: FNL Dist: 464 feet Direction: FWL
Sec: 26 Twp: 6S Rng: 97W

FNL/FSL

FEL/FWL

** If directional footage at Bottom Hole Dist: 1812 feet Direction: FNL Dist: 311 feet Direction: FWL
Sec: 26 Twp: 6S Rng: 97W

Field Name: GRAND VALLEY

Field Number: 31290

Federal, Indian or State Lease Number:

Spud Date: (when the 1st bit hit the dirt) 12/21/2017 Date TD: 12/26/2017 Date Casing Set or D&A: 12/27/2017

Rig Release Date: 07/09/2018 Per Rule 308A.b.

Well Classification:

☐ Dry ☐ Oil ☒ Gas/Coalbed ☐ Disposal ☐ Stratigraphic ☐ Enhanced Recovery ☐ Storage ☐ Observation

Total Depth MD 8892 TVD** 8753 Plug Back Total Depth MD 8779 TVD** 8640

Elevations GR 8322 KB 8352

Digital Copies of ALL Logs must be Attached per Rule 308A ☐

List Electric Logs Run:

CBL, NEU, (Triple Combo on 045-23418).

CASING, LINER AND CEMENT

Casing Type	Size of Hole	Size of Casing	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Top	Cmt Bot	Status
CONDUCTOR	30	20	54	0	100	218	0	100	VISU
SURF	14+3/4	9+5/8	40	0	2,500	866	662	2,552	CALC
1ST	8+3/4	4+1/2	11.6	0	8,828	949	4,583	8,892	CBL

STAGE/TOP OUT/REMEDIAL CEMENT

Cement work date: 12/23/2017

Method used	String	Cementing tool setting/perf depth	Cement volume	Cement top	Cement bottom
1 INCH	SURF	662	253	0	662

Details of work:

FORMATION LOG INTERVALS AND TEST ZONES

FORMATION NAME	Measured Depth		Check if applies		COMMENTS (All DST and Core Analysis must be submitted to COGCC)
	Top	Bottom	DST	Cored	
GREEN RIVER	0		NO	NO	
WASATCH G	4,346		NO	NO	
FORT UNION	4,639		NO	NO	
OHIO CREEK	5,861		NO	NO	
WILLIAMS FORK	6,034		NO	NO	
CAMEO	8,239		NO	NO	
ROLLINS	8,683		NO	NO	

Operator Comments:

All casing and cement information and formation tops are measured from KB. Per the approved Form 2 APD for the subject well, one gamma ray and one resistivity log was required for this multi-well pad.

No open hole Resistivity log with Gamma Ray was run on this well per rule 317.p.
A Triple Combination log was run on the Puckett 13D-26-697 (045-23418).

The well logs uploaded contain both the CBL and the Pulsed Neutron data.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Reed Haddock

Title: Sr. Regulatory Specialist Date: 9/6/2018 Email: rhaddock@caerusoilandgas.com

Attachment Check List

Att Doc Num	Document Name	attached ?			
<u>Attachment Checklist</u>					
	CMT Summary *	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
	Core Analysis	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
401499287	Directional Survey **	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>
	DST Analysis	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
	Logs	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>
	Other	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
<u>Other Attachments</u>					
2349834	CEMENT BOND/PULSED NEUTRON_LAS	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>
401499179	FORM 5 SUBMITTED	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>
401499193	CEMENT JOB SUMMARY_SURFACE	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>
401499288	DIRECTIONAL DATA	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>
401734722	CEMENT BOND/PULSED NEUTRON_PDF	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>
401755477	WELL LOCATION PLAT	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineering Tech	Corrected list all electric logs run abbreviation Corrected 1st string cement bottom per attached directional survey Corrected/split surface casing top out cement to Stage/Top Out/Remedial Cement Tab Passed engineering review	04/29/2020
Permit	<ul style="list-style-type: none"> Attached CBL/Neutron .las (401734726) is incomplete; deleted; complete version received and uploaded as doc 02349834. GPS "Date of Measurement" and "Operator's Name" corrected per attached plat; taken on Conductor. Surface string "Sacks of Cement" corrected from 866 to 1119 to include 253 sacks top-out. 	03/24/2020

Total: 2 comment(s)

