

Inspection Photos  
Operator: BP America  
API#: 067-06727  
Date: 4/28/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with sagebrush, sand dropseed, and milkvetch.



Photo 3. View of unmarked rig anchor outside of the fenced working area.



Photo 4. View of reference area vegetation comprised of open sagebrush and greasewood shrubland, with understory grasses and forbs such as sand dropseed and milkvetch.