

Inspection Photos
Location Name: Lamb Dalton Nesssu #13
Location ID: 317947



Photo 1 Updated WH sign



Photo 2 Stained soil and weeds have been removed from around WH

Inspection Photos
Location Name: Lamb Dalton Nessu #13
Location ID: 317947



Photo 3 loc pic WH and PU



Photo 4 Dead weeds have been removed from PU

Inspection Photos
Location Name: Lamb Dalton Nessu #13
Location ID: 317947



Photo 5 Electric panel LOTO in off position



Photo 6 Unused equipment: conduit/wiring sticking out of ground