

Inspection Photos
Location Name: Roy Dutcher Unit B #1
Location ID: 317870



Photo 1 WH sign faded and will need replaced in the near future



Photo 2 WH stained soil has been removed

Inspection Photos
Location Name: Roy Dutcher Unit B #1
Location ID: 317870



Photo 3 PU & WH



Photo 4 transformers, meter box and electric panel

Inspection Photos
Location Name: Roy Dutcher Unit B #1
Location ID: 317870



Photo 5 TB sign



Photo 6 TB

Inspection Photos
Location Name: Roy Dutcher Unit B #1
Location ID: 317870



Photo 7 Horizontal Heated separators



Photo 8 ECD

Location ID: 317870



Photo 9 Gas meter run, pig station



Photo 10 card inside of meter house

Inspection Photos
Location Name: Roy Dutcher Unit B #1
Location ID: 317870




Photo 11 Gas meter run