

Inspection Photos
Operator: BP America
API#: 067-08862
Date: 4/28/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the northern fill slope from the northeastern corner facing westward. Revegetation is progressing with grasses such as western wheatgrass.



Photo 3. View of reference area vegetation comprised of open sagebrush and greasewood shrubland, with understory grasses and forbs such as sand dropseed and milkvetch.