

Inspection Photos  
Location Name: Yocam 22-32  
Location ID: 331294



Photo 1 – Tank Battery Sign



Photo 2 – Pumping Unit



**Inspection Photos**  
**Location Name: Yocam 22-32**  
**Location ID: 331294**



**Photo 3 – Separator**



**Photo 4 – Produced Water, NFPA Label is peeling/fading**






**Inspection Photos**  
**Location Name: Yocam 22-32**  
**Location ID: 331294**




**Photo 5 – Stained Soil in between tanks**



**Photo 6 – Stained Soil at back end of the East Tank**



**Inspection Photos**  
**Location Name: Yocam 22-32**  
**Location ID: 331294**




**Photo 7 – Stained Soil at cleaned out plate on West Tank**




**Photo 8 – Stained Soil at cleaned out plate on West Tank**



**Inspection Photos**  
**Location Name: Yocam 22-32**  
**Location ID: 331294**



**Photo 9 – Stained Soil at Gas Engine**



**Photo 10 – Stained Soil at Gas Engine**

