

Inspection Photos
Location Name: Sam Funakoshi A #2
Location ID: 318430



Photo 1 WH sign.



Photo 2 WH & PU.

Inspection Photos
Location Name: Sam Funakoshi A #2
Location ID: 318430



Photo 3 Stained soil by WH.



Photo 4 Meter box , transformers and electric panel. Dead weeds inside fencing.