

Inspection Photos
Location Name: Hazel McHale #4 TB pics
Location ID: 318373



Photo 1 TB sign.

Photo 2 TB

Inspection Photos
Location Name: Hazel McHale #4 TB pics
Location ID: 318373



Photo 3 PW vessel.

Photo 4 Production lines/pump

Inspection Photos
Location Name: Hazel McHale #4 TB pics
Location ID: 318373



Photo 5 Gas meter run.

Photo 6 Horizontal Heated separator

Inspection Photos
Location Name: Hazel McHale #4 TB pics
Location ID: 318373



Photo 7 Stained soil by Horiz. Heated Sep.

Photo 8 Stained soil by Horiz. Heated Sep.