

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/30/2020

Submitted Date:

04/30/2020

Document Number:

701000599

FIELD INSPECTION FORM
 Loc ID 303263 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|-------|---------------------------------|---------|
| Beard, Alyssa | | regulatory@foundationenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 252781 | WELL | PR | 12/01/2019 | GW | 125-06657 | DEVLIN 12-5 | PR |

General Comment:

Routine Inspection

Location

| | | | |
|--------------------|-----------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Gravel road through pasture | | |
| Corrective Action | | Date: | |

Overall Good: ☒

| | | | |
|----------------------|-----------------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Lease sign mounted to fence | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Metal sign by water tank | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|---|-------|--|
| Fencing/: | | | |
| Type | LOCATION | | |
| Comment: | Metal fence around unit, wellhead, meter shed, VGS and water tank | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------------|--------------------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Prime Mover | # 1 | | |
| Comment: | Electric motor | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | Jensen unit | | |
| Corrective Action: | | Date: | |
| Type: Vertical Separator | # 1 | | |
| Comment: | Vertical gas separator by meter shed | | |
| Corrective Action: | | Date: | |

| | | |
|---------------------------|----------------|-------|
| Type: Ancillary equipment | # 1 | |
| Comment: | Electric panel | |
| Corrective Action: | | Date: |

Tanks and Berms:

| | | | | | |
|--------------------|---|----------|----------|---------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | OTHER | Open Top | | 39.654130,-102.211840 |
| Comment: | Fiberglass open top water tank 50% buried | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|---------|
| Condition | |
| Other (Content) | |
| Other (Capacity) | 210bbbs |
| Other (Type) | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 252781 | Type: | WELL | API Number: | 125-06657 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing. Casing production | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT