

Inspection Photos

Location Name: NEW ELK 24-16 FOLLOW UP

API#: 05-071-09473

INSP. #: 695102763



Colorado Oil & Gas Conservation Commission
37.15072, -104.94126, 2307.0m, 116°
2020/04/30 10:22:36



Colorado Oil & Gas Conservation Commission
37.15082, -104.94136, 2307.0m, 107°
2020/04/30 10:24:42

PHOTO 1: LOCATION

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: NEW ELK 24-16 FOLLOW UP

API#: 05-071-09473

INSP. #: 695102763



PHOTO 3: Stained soil around HYD skid. Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A CA DATE 5-7-20. THIS IS SECOND NOTICE FOR THIS CORRECTIVE ACTION.

PHOTO 4: STANDING OIL IN COMPRESSOR SKID. Comply with general provisions of the oil and gas act for wildlife protection. CA DATE 5-7-20.