

Inspection Photos
Location Name: NEW ELK 25-04
API#: 05-071-09535
INSP. #: 695102765



Colorado Oil & Gas Conservation Commission
37.14709, -104.95156, 2397.0m, 191°
2020/04/30 10:51:28



Colorado Oil & Gas Conservation Commission
37.14704, -104.95184, 2347.0m, 231°
2020/04/30 10:51:58

PHOTO 1: LOCATION


PHOTO 2: WELL SIGN

Inspection Photos

Location Name: NEW ELK 25-04

API#: 05-071-09535

INSP. #: 695102765



Colorado Oil & Gas Conservation Commission
37.14704, -104.95185, 2348.0m, 338°
2020/04/30 10:52:48



Colorado Oil & Gas Conservation Commission
37.14704, -104.95185, 2348.0m, 97°
2020/04/30 10:53:53

PHOTO 3: AREA OF IMPACTED SOIL AROUND COMPRESSOR SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 5-7-20. (REMOVE ALL IMPACTED SOIL ON LOCATION).

PHOTO 4: UNUSED EQUIPMENT STORED ON LOCATION. REMOVE UNUSED EQUIPMENT COMPLY WITH RULE 603.F. CA DATE 5-9-20.

Inspection Photos

Location Name: NEW ELK 25-04

API#: 05-071-09535

INSP. #: 695102765



Colorado Oil & Gas Conservation Commission
37.14704, -104.95185, 2348.0m, 287°
2020/04/30 10:53:13



Colorado Oil & Gas Conservation Commission
37.14704, -104.95185, 2348.0m, 8°
2020/04/30 10:52:16

PHOTO 5: TRASH INSIDE COMPRESSOR SOUND WALLS. REMOVE ALL TRASH IN AND AROUND LOCATION. COMPLY WITH RULE 603.F. CA DATE 5-9-20.

PHOTO 6: STANDING OIL IN COMPRESSOR SKID APPEARS AND ENGINE OIL IS BEING DRAINED INTO SKID AND LEFT. Comply with general provisions of the oil and gas act for wildlife protection. 5-7-20.