

Final Reclamation Inspection

April 30, 2020

Operator: PDC ENERGY INC - 69175

Location ID: 329181

Inspection Document #: 697501445

Weld County, CO

NENE Section 5 T3N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: BECKER #5-10
Location ID: 329181



Photo 1. Photo taken from the southern well location, facing North. Photo illustrates well location consists mostly of cheatgrass. Sand dropseed was observed but mostly in the reference areas.

Inspection Photos
Location Name: BECKER #5-10
Location ID: 329181



Photo 2. Photo taken from the associated offsite tank battery location, facing West. Photo illustrates Operator has failed to remove all equipment.

Inspection Photos
Location Name: BECKER #5-10
Location ID: 329181



Photo 3. Photo taken from the western associated offsite tank battery location, facing South. Photo illustrates Operator performed final reclamation activities with the evidence of drill rows; however, location consists mostly of weedy, annual vegetation (cheatgrass and flixweed) and bare ground.