

Final Reclamation Inspection

April 30, 2020

Operator: PDC ENERGY INC - 69175

Location ID: 306543

Inspection Document #: 697501449

Weld County, CO

SWNE Section 5 T3N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: BECKER #6-11I
Location ID: 306543



Photo 1. Photo taken from the well location access road and southern tank , facing West. Photo illustrates well location consists mostly of weedy, annual vegetation (cheatgrass and flixweed) and bare ground.

Inspection Photos
Location Name: BECKER #6-11I
Location ID: 306543



Photo 2. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: BECKER #6-11I
Location ID: 306543



Photo 3. Photo taken from the associated offsite tank battery location, facing West. Photo illustrates Operator has failed to remove all equipment.

Inspection Photos
Location Name: BECKER #6-11I
Location ID: 306543



Photo 4. Photo taken from the western associated offsite tank battery location, facing South. Photo illustrates Operator performed final reclamation activities with the evidence of drill rows; however, location consists mostly of weedy, annual vegetation (cheatgrass and flixweed) and bare ground.