

Inspection Photos
Location Name: UPRR 42 Pan AM "G" #3
Location ID: 318415




Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: UPRR 42 Pan AM "G" #3
Location ID: 318415



Photo 3 PU



Photo 4 Transformers, meter box and electric panel

Inspection Photos
Location Name: UPRR 42 Pan AM "G" #3
Location ID: 318415



Photo 5 TB sign

Photo 6 TB

Inspection Photos
Location Name: UPRR 42 Pan AM "G" #3
Location ID: 318415



Photo 7 Verical Separator house has been removed




Photo 8 flow line risers have been LOTO

Inspection Photos
Location Name: UPRR 42 Pan AM "G" #3
Location ID: 318415



Photo 9 Horizontal Heated Separator




Photo 10 flow line risers have been LOTO

Inspection Photos
Location Name: UPRR 42 Pan AM "G" #3
Location ID: 318415



Photo 11 Weeds have been removed from PW vessel berm



Photo 12 Gas meter run