

**Inspection Photos**  
**Location Name: Parker 44-15**  
**Location ID: 332886**



**Photo 1 WH sign**



**Photo 2 WH**

Inspection Photos  
Location Name: Parker 44-15  
Location ID: 332886



Photo 3 TB sign



Photo 4 excavation hole where crude tank was located

**Inspection Photos**  
**Location Name: Parker 44-15**  
**Location ID: 332886**



**Photo 5 unused removed/ replacement tank**




**Photo 6 PU**



# Inspection Photos Location Name: Parker 44-15 Location ID: 332886



Colorado Oil & Gas Conservation Commission  
 9124 Co Rd 21, Fort Lupton, CO 80621, USA  
 40.13272, -104.86958, 4917.9ft, 274°  
 05/04/2020 10:58:54



Colorado Oil & Gas Conservation Commission  
 9124 Co Rd 21, Fort Lupton, CO 80621, USA  
 40.13272, -104.86961, 4922.2ft, 256°  
 05/04/2020 10:59:21

Photo 7 Gas meter run

Photo 8 card inside meter house

**Inspection Photos**  
**Location Name: Parker 44-15**  
**Location ID: 332886**



**Photo 9 Vertical Heated Separator**



**Photo 10 unused tank equipment**