

Inspection Photos
Spill ID 449632
Remediation Project 10149
Inspection Date: 4/20/2020
All Photos taken by Kris Neidel



Photo #1 area of impact. Note evidence of soil being worked.





Inspection Photos
Spill ID 449632
Remediation Project 10149
Inspection Date: 4/20/2020
All Photos taken by Kris Neidel

Photo #2 40.133418,-108.913237. Area of previous impact.

Inspection Photos
Spill ID 449632
Remediation Project 10149
Inspection Date: 4/20/2020
All Photos taken by Kris Neidel



Photo #3 40.133438,-108.913292



Inspection Photos
Spill ID 449632
Remediation Project 10149
Inspection Date: 4/20/2020
All Photos taken by Kris Neidel



Photo #4. Chevron staff collecting sample from former spill path.



Inspection Photos
Spill ID 449632
Remediation Project 10149
Inspection Date: 4/20/2020
All Photos taken by Kris Neidel



Photo #5 40.133780,-108.912265. Close up of area of impact.
Note old tire tracks from skid steer that was used to till the spill
path.

Inspection Photos
Spill ID 449632
Remediation Project 10149
Inspection Date: 4/20/2020
All Photos taken by Kris Neidel



Photo #6 40.134137,-108.911903. wildlife present in Remediation Area.





Inspection Photos
Spill ID 449632
Remediation Project 10149
Inspection Date: 4/20/2020
All Photos taken by Kris Neidel

Photo #7 Close up of area of impact. Note old tire tracks from skid steer that was used to till the spill path.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Spill ID 449632
Remediation Project 10149
Inspection Date: 4/20/2020
All Photos taken by Kris Neidel



Photo #8 40.134185,-108.910465 area where the ditch from division I meet another drainage.





Inspection Photos
Spill ID 449632
Remediation Project 10149
Inspection Date: 4/20/2020
All Photos taken by Kris Neidel

Photo #9 40.134190,-108.910400





Inspection Photos
Spill ID 449632
Remediation Project 10149
Inspection Date: 4/20/2020
All Photos taken by Kris Neidel

Photo #10 40.134202,-108.910393

