

Final Reclamation Inspection

April 30, 2020

Operator: PDC ENERGY INC - 69175

Location ID: 322943

Inspection Document #: 697501459

Weld County, CO

NWSE Section 5 T3N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: BECKER #5-1
Location ID: 322943



Photo 1. Photo taken from the well location, facing South. Photo illustrates the well location consists mostly of weedy, annual vegetation and bare ground. Appears vehicle traffic has potentially compacted the reclamation area and comprised the success of revegetation.

Inspection Photos
Location Name: BECKER #5-1
Location ID: 322943



Photo 2. Photo taken from the associated tank battery, facing North. Photo illustrates the tank battery is still in use for another nearby well.