

Inspection Photos

Loc#335058

Operator: Caerus

Inspection Number: 692402123

Inspection Date: 4/23/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from Interim area to East.

April 23 ,2020



Photo#2:
View of Interim Area on Fill North side of Location.

Photo#3:
Insert; area of Cheat grass establishment.

April 23 ,2020



Photo#4:
NW corner of Pad where stormwater discharges.



Photo#5:
Erosion down gradient of Photo #4.

April 23 ,2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Alp Fee Loc#335058



Photo#6:
Erosion and non functioning BMP.

April 23 ,2020



Photo#7:
Sediment Migration.

Caerus Alp Fee Loc#335058



Photo#8:

Overwhelmed BMP South west of previous Photos.

April 23 ,2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Alp Fee Loc#335058