

Inspection Photos

Loc#334911

Operator: Caerus

Inspection Number: 692402126

Inspection Date: 4/23/20





Photo#1:
Overview of Location from Interim area to North.

April 23 ,2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus HMU Loc#334911



Photo#2:
North edge of Pad and stormwater concerns.



Photo#3:
Erosion tunneling.

April 23 ,2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus HMU Loc#334911



Photo#4:
Unmarked Anchor.

April 23 ,2020



Photo#5:
T Post Anchor.

Caerus HMU Loc#334911