

Inspection Photos

Location Name: JOHNSON A-66N64W /32SENW

Location #: 330219




Photo #1

Johnson A 32-06 (05-123-18645) Wellsite

Plugged & Abandoned | PA

~ 150 yds.

Reclamation progressing



Photo #2

QC USX A32-19 Battery site

Active

Formerly served:

Rubix A 32-03, 32-04, Johnson A 32-06

Plugged & Abandoned | PA