

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/04/2020

Submitted Date:

05/05/2020

Document Number:

696102899

**FIELD INSPECTION FORM**Loc ID 330218 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250841	WELL	SI	05/01/2019	OW	123-18644	RUBIX A 32-04	PA

**General Comment:**

This is a PLUGGED &amp; ABANDONED WELL inspection.

Well(s): 1: Plugged &amp; Abandoned | PA.

Battery: Active.

Centralized Battery serves 1 Location ID (420827).

(Well(s): 1: Producing | PR).

Centralized Battery formerly served 3 Location IDs (330217, 330218, 330219).

(Well(s): 3: Plugged &amp; Abandoned | PA).

Refer to Field Inspection Report doc. #696102895 and/or Location ID #420827 for Battery / Facility, Equipment info.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

# 0

Comment: [Plugged & Abandoned | PA. ALL equipment removed.](#)Corrective Action: Date: 

Type: Horizontal Heated Separator

# 0

Comment: [Plugged & Abandoned | PA. ALL equipment removed.  
Battery equipment reassigned to Location ID #420827.](#)Corrective Action: Date: 

Type: Emission Control Device

# 0

Comment: [Plugged & Abandoned | PA. ALL equipment removed.  
Battery equipment reassigned to Location ID #420827.](#)Corrective Action: Date: 

Type: Gas Meter Run

# 0

Comment: [Plugged & Abandoned | PA. ALL equipment removed.  
Battery equipment reassigned to Location ID #420827.](#)Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,

Comment: [Plugged & Abandoned | PA. ALL equipment removed.  
Battery equipment reassigned to Location ID #420827.](#)Corrective Action: Date: **Paint**Condition: Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	<input type="text"/>			

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	0				,	
Comment: <a href="#">Plugged &amp; Abandoned   PA. ALL equipment removed. Battery equipment reassigned to Location ID #420827.</a>						
Corrective Action:					Date:	

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 250841 Type: WELL API Number: 123-18644 Status: SI Insp. Status: PA

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 05/04/2020 at approximately 14:18 hrs. I, Bret Evins, conducted an on-site inspection at:            Operator Name: NOBLE ENERGY INC            Location Name: RUBIX-66N64W /32NWNW            Location ID: 330218            Well Name: Rubix A 32-04            API: 05-123-18644            Location County: Weld County, Colorado            Weather: Partly cloudy, damp from prior storm.</p> <p>While there, I observed:            Well(s): 1: Plugged &amp; Abandoned   PA.            Battery: Active.</p> <p>Centralized Battery serves 1 Location ID (420827).            (Well(s): 1: Producing   PR).</p> <p>Centralized Battery formerly served 3 Location IDs (330217, 330218, 330219).            (Well(s): 3: Plugged &amp; Abandoned   PA).</p> <p>Refer to Field Inspection Report doc. #696102895 and/or Location ID #420827 for Battery / Facility, Equipment info.</p> <p>WELL STATUS COMMENT:            Plugged &amp; Abandoned   PA.            Well appears to be cut / capped.            Form 42 doc. #402040851 indicates plugging, cut/cap start date: 05/17/2019. Approved.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	05/05/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696102900	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5142064">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5142064</a>