

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/04/2020

Submitted Date:

05/05/2020

Document Number:

696102901

FIELD INSPECTION FORM

Loc ID 330219 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250842	WELL	PR	04/01/2018	OW	123-18645	JOHNSON A 32-06	PA

General Comment:

This is a PLUGGED & ABANDONED WELL inspection.

Well(s): 1: Plugged & Abandoned | PA.

Battery: Active.

Centralized Battery serves 1 Location ID (420827).

(Well(s): 1: Producing | PR).

Centralized Battery formerly served 3 Location IDs (330217, 330218, 330219).

(Well(s): 3: Plugged & Abandoned | PA).

Refer to Field Inspection Report doc. #696102895 and/or Location ID #420827 for Battery / Facility, Equipment info.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 0		corrective date
Comment:	Plugged & Abandoned PA. ALL equipment removed.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 250842 Type: WELL API Number: 123-18645 Status: PR Insp. Status: PA

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 05/04/2020 at approximately 13:55 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: JOHNSON A-66N64W /32SENW Location ID: 330219 Well Name: Johnson A 32-06 API: 05-123-18645 Location County: Weld County, Colorado Weather: Partly cloudy, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Active.</p> <p>Centralized Battery serves 1 Location ID (420827). (Well(s): 1: Producing PR).</p> <p>Centralized Battery formerly served 3 Location IDs (330217, 330218, 330219). (Well(s): 3: Plugged & Abandoned PA).</p> <p>Refer to Field Inspection Report doc. #696102895 and/or Location ID #420827 for Battery / Facility, Equipment info.</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Well appears to be cut / capped. Form 42 doc. #402031701 indicates plugging, cut/cap start date: 05/06/2019. Approved.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	05/05/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696102902	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5142065