

Inspection Photos

Location ID, Name: 409821, MORNING FRESH-63N66W 10SESW



Photo 1 05-123-22610
MORNING FRESH
14-10X



Photo 2 Battery



Photo 3 ECD

Inspection Photos Location ID, Name: 409821, MORNING FRESH-63N66W 10SESW

Station # 409821	Ad	Gr	Station Name Morning Fresh 14-101	Sec 10	Twp/Ship Pa 30/16
Radio #			Producer Name KMA MC	County 1/20	State CO
Transmitter / Module # T102228281	Federal #		State #		
Static / Span 300	Up / Dwn UP	Diff / Span 250	Temp / Span 150	Absolute 12.2	API #
Test Date 8/19/10	OP Size 1.500	Beta .72	Sample Date	H2S	H2S
8-11-11	1.510	.72			
8-13-12	1.500	.72			
8-1-13	1.500	.72			
8-5-14	1.500	.72			
8-14-15	1.50	.72			
8-11-16	1.50	.72			
8-25-17	1.50	.72			
8-10-18	1.50	.72			
8-16-19	1.50	.72			

Photo 4 GMR