

Inspection Photos

Location ID, Name: 328405, HSR-EDDINGTON-63N66W 3NESE



Photo 1 Battery



Photo 2 Production Equipment



Photo 3 ECD

Inspection Photos

Location ID, Name: 328405, HSR-EDDINGTON-63N66W 3NESE

Static / Span	Up/ Dwn	Diff / Span	Temp / Span	H ₂ S
0-30	Up	0-950	0°-150°	
3-2-13	1.250			
9-10-13	1.250			
3-4-14	1.250			
5-5-14	1.250			
3-10-15	1.250			
9-23-15	1.250			
3-28-15	1.250			
9/14/16	1.250			
3/23/17	1.250			
1/20/17	1.250			
L-R				
ACE	ACCESSION			
STATION	8410005			
LOC	8			
DATE	05/05/2020			

Photo 4 GMR Card Front

Test Date	OP Size	Beta	Sample Date	H ₂ S	Sample Date	H ₂ S
3/22/18	1.250		3/22/18			
9-21-18	1.250		9-25-18			
3/6/19	1.250		3/6/19			
9/11/19	1.250		9/11/19			
3-11-20	1.25		UPGA			

Photo 5 GMR Back



Photo 6 05-123-15950
HSR-EDDINGTON
9-3