FORM INSP Rev X/15	State of Colorado Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109 **FIELD INSPECTION FORM**	Inspection Date: 05/05/2020 Submitted Date: 05/05/2020 Document Number: 690005682

Loc ID 309856	Inspector Name: Carlile, Craig	On-Site Inspection ☐ 2A Doc Num:

Operator Information:

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER   State: CO   Zip: 80217-

Status Summary:

☐ THIS IS A FOLLOW UP INSPECTION

☐ FOLLOW UP INSPECTION REQUIRED

☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4   Number of Comments

0   Number of Corrective Actions

☐ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
398	WELL	PR	10/01/2019	GW	123-25470	LUDWIG H 6-18	PR

General Comment:

Inspector Name: Carlile, Craig

Location				

Overall Good: ☒

Signs/Marker:

Type	BATTERY			
Comment:				
Corrective Action:			Date:	
Type	WELLHEAD			
Comment:				
Corrective Action:			Date:	
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:			Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good: ☒

Spills:

Type	Area	Volume			

In Containment: No

Comment:

☐ Multilple Spills and Releases?

Fencing/:

Type	WELLHEAD			
Comment:				
Corrective Action:			Date:	

Equipment:

				corrective date
Type: Horizontal Heated Separator	# 1			
Comment:				
Corrective Action:			Date:	
Type: Bird Protectors	# 2			
Comment:				
Corrective Action:			Date:	
Type: Gas Meter Run	# 2			
Comment:				
Corrective Action:			Date:	
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:			Date:	
Type: Emission Control Device	# 1			

Inspector Name: Carlile, Craig

	Comment:			
	Corrective Action:		Date:	

Type: Pig Station		# 1			
	Comment:				
	Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type		Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV CONCRETE			,	

	Comment:			
	Corrective Action:		Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	

	Comment:	Shared with crude oil tank.	
Corrective Action:		Date:	

Contents	#	Capacity	Type		Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST			40.257880,-104.705710	

	Comment:			
	Corrective Action:		Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Suffcient	Base Sufficient	Adequate	

	Comment:		
Corrective Action:		Date:	

Venting:

	Yes/No	NO		
	Comment:			
Corrective Action:			Date:	

Flaring:

Type	Ignitor/Combustor	

Inspector Name: Carlile, Craig

Comment:		
Corrective Action:	Date:	

Inspected Facilities									
Facility ID:	398	Type:	WELL	API Number:	123-25470	Status:	PR	Insp. Status:	PR

Producing Well	
Comment:	PR
Corrective Action:	Date:

COGCC Comments		
Comment	User	Date
Routine wellhead and battery inspeciton.	carlilec	05/05/2020

Attached Documents

You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:

Document Num	Description	URL
690005683	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5142294