

Inspection Photos

Loc#334940

Operator: Caerus

Inspection Number: 692402126

Inspection Date: 4/23/20





Photo#1:
Overview of Location from entry to South.

April 23 ,2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus HMU Loc#334940



Photo#2:
Cheat grass establishment.

Photo#3:
Cheat grass establishment.

April 23 ,2020



Photo#4:
Two unknown Risers on site.

April 23 ,2020



Photo#5:
Close up of Riser.

Caerus HMU Loc#334940