

Inspection Photos

Loc#334940

Operator: Caerus

Inspection Number: 692402127

Inspection Date: 4/23/20





Photo#1:
Overview of Location to Northwest.

April 24 ,2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Benzel Loc#334967




Photo#2:
Area no longer needed for use re-vegetated on adjacent Location.

April 24 ,2020



Photo#3:
Area no longer needed for use, not re-vegetated on subject Location.



Photo#4:
Check to determine if Liner leaking.



Photo#5:
Check to determine if Liner leaking.

April 24 ,2020



Photo#6:
Fill slope and BMPs being de-stabilized, not functioning.

April 24 ,2020



Photo#7:
Fill slope and BMPs being de-stabilized, not functioning.



Photo#8:
Fill slope and BMPs being de-stabilized, not functioning.

April 24 ,2020



Photo#9:
Fill slope and BMPs being de-stabilized, not functioning.



Photo#10:
Fill slope and BMPs being de-stabilized, not functioning.

Photo#11:
Fill slope and BMPs being de-stabilized, not functioning.

April 24 ,2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Benzel Loc#334967