

Inspection Photos
Location Name: McCoy Phillip unit E A 1 TB
Location ID: 332868



Photo 1 TB signs

Photo 2 TB

Inspection Photos
Location Name: McCoy Phillip unit E A 1 TB
Location ID: 332868



Photo 3 LACT house



Photo 4 FWKO/ Vert. separator

Inspection Photos
Location Name: McCoy Phillip unit E A 1 TB
Location ID: 332868



Photo 5 compressor

Photo 6 ECD

Inspection Photos
Location Name: McCoy Phillip unit E A 1 TB
Location ID: 332868




Photo 7 Horizontal Heated Separators

Photo 8 Horizontal Heated Separators

Inspection Photos
Location Name: McCoy Phillip unit E A 1 TB
Location ID: 332868



Colorado Oil & Gas Conservation Commission
 10440 Co Rd 22, Fort Lupton, CO 80621, USA
 40.14305, -104.85973, 4894.0ft, 87°
 05/05/2020 10:49:10



Colorado Oil & Gas Conservation Commission
 10440 Co Rd 22, Fort Lupton, CO 80621, USA
 40.14304, -104.85981, 4901.2ft, 88°
 05/05/2020 10:49:31

Photo 9 Gas meter run

Photo 10 card inside of meter house