

Inspection Photos
Location Name: Vonasek #8
Location ID: 336210



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Vonasek #8
Location ID: 336210



Photo 3 unused electric panel



Photo 4 stained soil under gas engine skid

Inspection Photos
Location Name: Vonasek #8
Location ID: 336210



Photo 5 PU pulley belts have no safety guards covering them

Photo 6 PU pulley belts have no safety guards covering them