

Inspection Photos
Location Name: A.D. Jeffers A #1
Location ID: 323176



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: A.D. Jeffers A #1
Location ID: 323176



Photo 3 TB sign



Photo 4 TB

Inspection Photos
Location Name: A.D. Jeffers A #1
Location ID: 323176



Photo 5 TB placards faded/falling off



Photo 6 PU gear box leak

Inspection Photos
Location Name: A.D. Jeffers A #1
Location ID: 323176



Photo 7 Stained ground/soil under PU gear box



Photo 8 stained soil under PU gas engine skid

Inspection Photos
Location Name: A.D. Jeffers A #1
Location ID: 323176



Photo 9 ECD



Photo 10 Horizontal Heated separator

Inspection Photos
Location Name: A.D. Jeffers A #1
Location ID: 323176



Photo 11 Gas meter run