

Inspection Photos
Location Name: Energy Minerals B #1
Location ID: 318873



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Energy Minerals B #1
Location ID: 318873



Photo 3 transformers meter box and electric panel



Photo 4 TB sign

Inspection Photos
Location Name: Energy Minerals B #1
Location ID: 318873



Photo 5 TB

Photo 6 PW

Inspection Photos
Location Name: Energy Minerals B #1
Location ID: 318873



Photo 7 stained soil under crude tank valve



Photo 8 stained soil under aux. skid engine

Inspection Photos
Location Name: Energy Minerals B #1
Location ID: 318873



Photo 9 stained soil under gas meter run



Photo 10 Gas meter run

Inspection Photos
Location Name: Energy Minerals B #1
Location ID: 318873



Photo 11 ECD



Photo 12 Horizontal Heated Separator